

Hyundai i20

Comfort 1.0 T-GDi 7DCT

Gasoline - Automatic - 15km - 04/2026

Ref 60670



[All images](#)

Hyundai i20

Comfort 1.0 T-GDi 7DCT

Gasoline - Automatic - 15km - 04/2026

Ref 60670

Description

Make	Hyundai
Model	i20
Description	Comfort 1.0 T-GDi 7DCT
Mileage	15 km
Type	Passenger car
Body type	Hatchback
Doors	5
Seats	5
Exterior color	Black
Interior color	Grey
Upholstery	Cloth

Technical

Fuel type	Gasoline	Gears	7
Gearbox	Automatic	Cylinders	0
Cylinder capacity	998 cc	Horse power	90 hp
Power KW	66 kw		
Drive train	Front		

Dimensions

Weight empty	1195 kg
--------------	---------

Hyundai i20

Comfort 1.0 T-GDi 7DCT

Gasoline - Automatic - 15km - 04/2026

Ref 60670

Registration and Warranty

First Registration 30-04-2026

Warranty start 17-04-2026

Options

Comfort

Seat heating front

Steering wheel leather

Mirrors heated

Central locking

Steering wheel heated

Mirrors electrical adjustable

Seats rear folding

Sensor interior light

Safety

Cruise control

Parking assist sensor rear

Alarm

ABS

Emergency brake assist

Isofix

Parking assist camera

Traffic sign recognition

High beam assist

ESP

Lane departure warning system

Infotainment

Apple CarPlay / Android Auto

DAB radio

Touch screen

Multifunctional steering wheel

Navigation system

Bluetooth

USB

On-board computer

Extras

Tinted windows

Hyundai i20

Comfort 1.0 T-GDi 7DCT

Gasoline - Automatic - 15km - 04/2026

Ref 60670

Equipment

Luggage compartment cover

ESP

Power steering

Multifunction steering wheel

Drowsiness warning system

Apple Car Play

On-board computer

DAB receiver

Android Auto

Light sensor

Emergency brake assist (F.A.)

Electric windows front and rear

Lane departure warning

Virtual Cockpit

Touchscreen

Central locking with radio

15-inch wheels The vehicle sustained minor hail damage. The repairs have already been professionally completed. A depreciation of 350 € net has already been factored into the purchase price. Please pass this information on to your customers. The vehicle was affected by light hail. The repairs have already been professionally completed. A depreciation of €350 net has already

Heated exterior mirrors

Color glazing

Heated front seats

Stability control

Height-adjustable driver's seat

Traffic sign recognition

Electrically adjustable exterior mirrors

Navigation system

Bluetooth

Leather steering wheel

The vehicle sustained minor hail damage. The repairs have already been professionally completed. A depreciation of 350 € net has already been factored into the purchase price. Please pass this information on to your customers.

Air conditioning

Height-adjustable steering wheel

Split rear bench seat

Steering wheel heating

Reversing camera

Metallic

been factored into the purchase price. Please pass this information on to your customers.

Cruise control system

Rear parking aid

Driving profile selection (Drive Mode Select)

Area monitoring system (Front Assist)

Passenger airbag can be deactivated

USB connection

High beam assistant (Light Assist)

Child seat preparation (ISOFIX)

6 Airbags

ABS

5 head restraints

Alarm system

Upholstery fabric

Image gallery

























