

Hyundai i20

Comfort 1.0 T-GDI Automatik

Gasoline - Automatic - 22506km - 12/2024

Ref 74256



[All images](#)

Hyundai i20

Comfort 1.0 T-GDI Automatik

Gasoline - Automatic - 22506km - 12/2024

Ref 74256

Description

Make	Hyundai
Model	i20
Description	Comfort 1.0 T-GDI Automatik
Mileage	22506 km
Type	Passenger car
Body type	Compact / Citycar
Doors	5
Seats	5
Exterior color	Green
Interior color	Grey
Upholstery	Cloth

Technical

Fuel type	Gasoline	Gears	7
Gearbox	Automatic	Cylinders	0
Cylinder capacity	998 cc	Horse power	101 hp
Power KW	74 kw		
Drive train	Front		

Dimensions

Weight empty	1225 kg
--------------	---------

Hyundai i20

Comfort 1.0 T-GDI Automatik

Gasoline - Automatic - 22506km - 12/2024

Ref 74256

Registration and Warranty

First Registration 17-12-2024

Warranty start 17-12-2024

Options

Comfort

Steering wheel leather
Mirrors heated
Central locking
Armrest
Mirrors electrical folding

Mirrors electrical adjustable
Seats rear folding
Start/stop system
Sensor interior light

Safety

Cruise control
Parking assist camera
Traffic sign recognition
Lights LED daytime running
Blind spot monitor
Isofix

Lights LED
Parking assist sensor rear
Alarm
High beam assist
Lane departure warning system

Infotainment

Apple CarPlay / Android Auto
DAB radio
Touch screen
USB
On-board computer

Navigation system
Bluetooth
Radio
Multifunctional steering wheel

Extras

Alloy wheels

Tinted windows

Hyundai i20

Comfort 1.0 T-GDI Automatik

Gasoline - Automatic - 22506km - 12/2024

Ref 74256

Equipment

Leather steering wheel	Luggage compartment cover
Heated exterior mirrors	Electric windows front and rear
Air conditioning	Electrically folding exterior mirrors
Lane departure warning	Color glazing
Height-adjustable steering wheel	Virtual Cockpit
Multifunction steering wheel	Automatic start/stop
Split rear bench seat	Touchscreen
Central locking with radio	Reversing camera
- Repainted - Paint residue on various parts - Paint defects on the front bumper and the right rear door - Scratches on the trunk lid - Color difference between the bumper and the wheel well The vehicle was affected by light hail. The repairs have already been professionally completed. A depreciation of €350 net has already been factored into the purchase price. Please pass this information on to your customers.	16-inch wheels
LED headlights	Drowsiness warning system
Cruise control system	LED daytime running lights
Height-adjustable driver's seat	LED rear lights
Rear parking aid	Driving profile selection (Drive Mode Select)
Area monitoring system (Front Assist)	Passenger airbag can be deactivated
USB connection	High beam assistant (Light Assist)
Child seat preparation (ISOFIX)	Apple Car Play
6 Airbags	Traffic sign recognition
Darkened side/rear window	On-board computer
Electrically adjustable exterior mirrors	DAB receiver
Navigation system	Radio

5 head restraints

Bluetooth

Center armrest

Upholstery fabric

Light sensor

Android Auto

Alarm system

Cornering/turning lights

LM rims

Image gallery































